

Wolframierz  
X2  
O2 O1

Zasilanie  
X1  
O2 O1

I<sub>-</sub>

I<sub>+</sub>

U<sub>+</sub>

U<sub>-</sub>

Mol tomierz




Zasilanie



D3



D4 1N4148 48



4046N

U3



RAD\_DY-CN\_20MM